



State of Utah

Department of
Natural Resources

ROBERT L. MORGAN
Executive Director

Division of
Oil, Gas & Mining


LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

June 7, 2004

TO: Minerals File

FROM: Doug Jensen, Senior Reclamation Engineer 

SUBJECT: Site Inspection, Pelican Point Rock Products, Pelican Point Quarry, M/049/011, Utah County, Utah

Date of Inspection: June 4, 2004
Time of Inspection: 8:30 a.m.
Conditions: Sunny, warm
Participants: Doug Jensen, Lynn Kunzler, DOGM

Purpose of Inspection:

Evaluate the site for bond escalation purposes.

Getting to the site:

The site is located near highway U-68, approximately three miles south of Saratoga Springs.

Observations:

The site was active at the time of our inspection. We stopped at the scales house to check in. We talked to Amy to inquire if Justin Cozad was on site. He was off-site at the time of our visit; therefore, we asked for permission to tour the site to check conditions.

We drove around several areas of the mine to assess the overall size of recent operations. The quarry operations were mainly centralized in the main quarry face; there has been a road constructed above the highwall. Access to this area will allow the operator to take material from the top of the highwall.

Much of the equipment was down for repairs at the time of the visit, with only one loader operating. It was taking material from the base of the highwall and feeding a crusher at the upper level.

Page 2

Pelican Rock Products

M/049/011

Inspection Date: June, 2004; Report Date: June 21, 2004

There are quite a few areas around the site that appear to have been disturbed recently. But until we receive the requested map of the site, it is difficult to tell if all the disturbances fall within the permitted area.

Pictures were taken during the visit and are included in this report.

Conclusions and Recommendations:

A notice was sent on August 19, 2003, requesting an updated map for use by the Division to escalate the bond. To date, this map has not been received. The operator needs to submit the required material as soon as possible.

Once the map is received it may be necessary to revisit the site to correlate the on-ground disturbances and the map.


DJ:jb

Attachments: Photos

cc: Justin Cozad, Pelican Point Rock Products

John Blake, SITLA (ML-46040)

O:\M049-Utah\m0490011-pelicanpoint\Inspections\insp-06042004.doc





6/4/2004

